







30 min



G		7x34	x4
H		15x12	x4
J		3,5x40	x16
C		7x50	x8
R		4mm	x1


Aa		10x40	x6
Ca		1897	x2
Ba		120x30x6	x2
Ga		3,5x16	x8
Ha		D26	x4

①




Aa		10x40	x6
----	--	-------	----

②



G		7x34	x4
---	--	------	----

3




H



15x12

x4

4



NB!

Ba



120x30x6

x2


J



3,5x40


x16


5




Ca		1897	x2
----	--	------	----

6



C		7x50	x8
---	---	------	----

7



Ha		D26	x4
Ga		3,5x16	x8