











Aa		8x20	x8
Ba		8x30	x32
Ca		7x30	x6
E		7x50	x4
Ea		M6x35	x2
Fa		M6x8x15x15	x2
Ga		7x34	x14
Ha		15x12	x14
G		5x38	x31
Ja		5x50	x4
Ka		21x21x16	x3
La		3,5x15	x6
Ma		6,5x27	x2
Pa		10x11	x2


Q		3,5x40	x19
Oa		3,5x16	x21
Ra		D19x6	x4
P		D13	x2
Z		D20	x2
M		D4x13	x3
O		D15x18	x2
V		D26	x2
U		D35	x4
WS		11/6,2x9	x8
T		4mm	x2

1




Aa		8x20	x8
Ba		8x30	x28

2




Ca		7x30	x6
----	---	------	----

3




E		7x50	x2
M		D4x13	x1
P		D13	x2

4




Ga		7x34	x4
----	---	------	----

5



G		5x38	x4
Ha		15x12	x4

6




Ga



7x34

x4

7




Ha



15x12




x4

8




G		5x38	x2
Ga		7x34	x2

9




Ka		21x21x16	x3
La		3,5x15	x6
Ha		15x12	x2
Z		D20	x2

10






E		7x50	x2
M		D4x13	x2
V		D26	x2
Oa		3,5x16	x4

11




Fa		M6x8x15	x2
Ea		M6x35	x2
O		D15x18	x2



12



- 37 - 370x70x17mm 6pcs.
 38 - 590x70x17mm 3pcs.
 39 - 590x70x17mm 2pcs.
 40 - 747x70x17mm 5pcs.
 41 - 780x90x17mm 2pcs.
 42 - 780x70x17mm 4pcs.





Q x14





Ra		D19x6	x4
Oa		3,5x16	x17
G		5x38	x17
Ja		5x50	x4
Q		3,5x40	x19

13






Ma		6,5x27	x2
----	---	--------	----

14





Pa		10x11	x2
----	---	-------	----

15





G		5x38	x4
---	---	------	----

16




Ga		7x34	x4
----	---	------	----

17




Ba		8x30	x4
----	---	------	----

18






G		5x38	x4
---	---	------	----

19



Ha		15x12	x4
----	---	-------	----

20



WS		11/6,2x9	x8
U		D35	x4